

HZDS

Hitachi B&W / Sulzer Information of Engine Parts

Ref.No.: HZDS97-04, Issued Date: Aug. 1997

Title

New life to your maneuvering system !

Engine Type : All Type Engines

Recently, on several ships after around 10 years service, difficulties in starting and stopping of the main engine due to malfunction of maneuvering system have been reported.

As a result of investigation, causes have been revealed to be:

- Wear of pins, bushes and so forth
- Leakage due to deterioration of packings on valves
- Vibration of equipment due to loosening of bolts
- Deterioration of electric equipment

10 years after the delivery,

Now is just time for giving new life to your maneuvering system.

— Check — Repair — Readjust —

Total systematic maintenance is essential.

- Pneumatic system
- Electric system
- Governor
- Mechanical system

Only we, as mother works of your engine, can do all together.

Hitachi Zosen Diesel Service Corporation

Tokyo Office
Palace Side Bldg.
1-1-1, Hitotsubashi, Chiyoda-ku,
Tokyo, 100 Japan
TEL : +81-3-3215-1722
FAX : +81-3-3217-8588
TLX : 222-2156

Osaka Office
2-3-81, Kizugawa, Naniwa-ku,
Osaka 556 Japan
TEL : +81-6-562-3411
FAX : +81-6-562-2900
TLX : 524-2101

Singapore Office
15, Benoi Road, Singapore,
6298888
TEL : +65-863-1490
FAX : +65-861-7579
TLX : HZSIN RS 21906