

# Modification & Standardization of Piston Rod Stuffing Box Rings


Engine Type:K/L/S50-60-70-80MC(E)

[Part 2]

We have introduced following new standard on the stuffing box rings, in order to unify them in accordance with our accumulated experiences.

The new standard will contribute to our efficient stock control and thus to our improved service to our client for the quick delivery.

Our supply of stuffing box rings in future will be based on this new standard and, in this connection, we appreciate our client's good understanding and support.



For detail please turn over.

### Hitachi Zosen Diesel Service Corporation

Tokyo Office

Palace Side Bldg.

1-1-1, Hitotsubashi, Chiyoda-ku,

Tokyo, 100 Japan

TEL : +81-3-3215-1722

FAX : +81-3-3217-8588

TLX : 222-2156

Osaka Office

2-3-81, Kizugawa, Naniwa-ku,

Osaka, 556 Japan

TEL : +81-6-562-3411

FAX : +81-6-562-2900

TLX : 524-2101

Singapore Office

15, Benoi Road, Singapore,

6298888

TEL : +65-863-1490

FAX : +65-861-7579

TLX : HZSIN RS 21906/21213