

Title

Repair of Main Engine Parts

**How do you manage quality control
of repaired main parts?**

We have mainly been to supply our clients with new, genuine parts, however to support the needs of our clients, we have set up a technically qualified repair system for the following parts.
(The repair history is controled with Charge No.)

1) Cylinder cover	Welding repair	
2) Piston crown	Welding repair	(Inconel also possible)
3) Piston rod	Welding repair	
4) Valve spindle and seat for exhaust valve	Welding repair	(Stellite, Colmonoi, Inconel, Nimonic also possible)
5) Fuel valve, Fuel pump	Inspection/Repair	
6) Fuel/Exhaust high pressure pipe.	Repair	

Furthermore, we will be happy to discuss the repair of the other parts with you.

Hitachi Zosen Diesel Service Corporation

Tokyo Office
Palace Side Bldg.
1-1-1, Hitotsubashi, Chiyoda-ku, Tokyo, 100 Japan
TEL : +81-3-3215-1722
FAX : +81-3-3217-8588
TLX : 222-2156

Osaka Office
2-3-81, Kizugawa, Naniwa-ku, Osaka 556 Japan
TEL : +81-6-562-3411
FAX : +81-6-562-2900
TLX : 524-2101

Singapore Office
15, Benoi Road, Singapore, 6298888
TEL : +65-863-1490
FAX : +65-861-7579
TLX : HZSIN RS 21906